

Oil Field Environmental Incident Summary

Incident: 20150222110900 **Date/Time of Notice:** 02/22/2015 11:09

Responsible Party: Liberty Oilfield Services

Well Operator: CONTINENTAL RESOURCES, INC.

Well Name: RENNERFELDT 6-30H1

Field Name: BROOKLYN

Well File #: 29193

Date Incident: 2/21/2015

Time Incident: 16:31

Facility ID Number:

County: WILLIAMS

Twp: 155

Rng: 98

Sec: 19

Qtr:

Location Description:

Submitted By: Timothy Ilse

Received By:

Contact Person: Frank Rodas
5018 142nd Ave NW
Williston, ND 58801

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - On Facility Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine						
Other	45	Barrels	45	Barrels	45	barrels

Description of Other Released Contaminant:

FR water, fresh water with friction reducer added.

Inspected:

Written Report Received: 9/20/2016

Clean Up Concluded: 3/2/2015

Risk Evaluation:

None

Areal Extent:

A 80 ft. by 50 ft. area

Potential Environmental Impacts:

Well site soil

Action Taken or Planned:

Water was sucked up and placed in side tank, remaining water froze and will be removed weather permitting.

Wastes Disposal Location: SWD

Agencies Involved: Called Jim Pots @ 20:28 2/21/15

Updates

Date: 2/23/2015 **Status:** Reviewed - Assigned to Other Agency

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to an on-location valve/piping leak, apparently occurred during fracking activities but remained on location within the diking according to the report. NDIC retains oversight.